

Treated Pine Trestle Bench Assembly Instructions

Please read through instructions entirely before beginning assembly.

Parts

Bench Top- 1
Leg Assemblies-2
Leg Feet- 2
2x4 Spreader-1

Hardware

20- 2 1/2" Screws
(squarehead bit included)

Step 1. Attach the feet to the leg assemblies using eight (8) 2 1/2" screws in the pre-drill holes. . Four screws for each foot.

Step 2. Attach the leg assembly to the bench top. Make sure the leg foot is on the outside of the leg assembly. Lay the bench top upside-down on a clean flat surface. (We recommend using the box the product was shipped in) Place the leg assembly on the inside of the bench support and attach by using four (4) 2 1/2" screws through the pre-drilled hole. Repeat with the other leg assembly.



Step 3. Step 3. Place the 2x4 spreader between the leg assemblies. (Having a second person to help you makes this step easier.) Attach the 2x4 spreader to the leg assembly by lining up the spreader with the pre-drilled holes in the leg assemblies. Attach the 2x4 spreader by using four (4) 2 1/2" screws. Two per side.

